

HAAKE Viscometer 7 R+

**Location of Machine:** Composites Lab, RFM 1218

**Location of SOP and Machine Operating & Safety Manual:** Composites Lab website under resources; Composites Lab TRACS site; and Hardcopy near machine.

**Emergency Contact:**

- Call 911
- Call EHS & Risk Management at 512-245-3616
- Call Head Lab Technician, Dr. Ray Cook (office 512-245-2050)
- Call Dr. Jitendra S Tate (office 512-245-4872)

**Before using this machine:**

- You must have permission from Dr. Tate.
- You must have received formal training from technician or, trained research student (designated by Dr. Tate) related to machine safety and operation.
- You must read and understand **SOP and Machine Cleaning Manual.**
- You must use this machine under direct supervision of Dr. Tate or, Dr. Cook or, trained research student (designated by Dr. Tate).
- You must have signed “Lab Rules” document with Dr. Tate. This document must be signed every semester fall, spring, and summer (as applicable).
- If you do NOT follow above instructions you will be held responsible for your own safety and damages.

**Safety Precautions:**

Protective Equipment: Prior to performing this procedure, the following personal protective equipment must be obtained and ready for use: **Gloves, Safety Goggles, Face Mask, Lab Coat.**

**Important Safeguards:**

1. Prior to performing this procedure, the following safety equipment must be accessible and ready for use: (e.g. chemical fume hood, biological safety cabinet, laminar flow hood, chemical spill kits) **Fume hood**
2. All liquids should be drained to containers for chemical disposal and properly marked.
3. In the event that a hazardous material spill during this procedure, be prepared to clean with cleaner according to MSDS of materials used.



### **General Information**

Viscosity is a measure of the resistance of a fluid which is being deformed by either shear stress or tensile stress. Viscosity and viscoelastic behavior of resins are very critical in composites manufacturing. Our lab is equipped with a classic rotational viscometer for the fast determination of viscosity as defined in ISO 2555 and more ASTM standards. For the determination of the rheological properties of a substance the measuring range can be changed by using a different speed or by a change of the spindle. The selection depends on the standard to be followed.

### **Specifications:**

Operating Temperature Range: -20 to 100°C

Reproducibility:  $\pm 1\%$


Hertz: 50-60Hz

Speed Range: 0.5-800rpm

Torque Range: 0.1-30mNm

Typical Testing Time: 1 min

Viscosity Range 1-1,000,000 mPas

Viscometer Operating procedure	
<ol style="list-style-type: none"><li>1. Viscometer Assembly<ol style="list-style-type: none"><li>a. Attach vertical pole to the base using the wrench provided in the case</li><li>b. Attach the viscometer to the vertical pole</li><li>c. Connect power cable to the viscometer</li><li>d. <u>Optional (if needed):</u> Attach the thermometer to the back panel</li><li>e. <u>Optional (only for large beakers):</u> Attach the frame to the viscometer</li></ol></li></ol>	
<ol style="list-style-type: none"><li>2. Turn on the viscometer<ol style="list-style-type: none"><li>a. Plug in the power cable to 110 V power outlet</li><li>b. Turn of switch on the back panel of the viscometer</li></ol></li><li>3. Calibration<ol style="list-style-type: none"><li>a. After the viscometer is turned on the following message will appear: "Calibration is out of date, remove spindle and press enter"</li><li>b. Make sure the spindle is not attached</li><li>c. Press enter</li></ol></li></ol>	
<ol style="list-style-type: none"><li>4. Starting up<ul style="list-style-type: none"><li>• Selected required spindle type from the case (Usually: R2-largers)</li><li>• Attach the spindle. <u>Note: Spindle has left-handed thread</u></li><li>• The machine is ready to use</li></ul></li></ol>	
<ol style="list-style-type: none"><li>5. Placing the beaker</li></ol>	

<ol style="list-style-type: none"><li>a. Raise the viscometer to the highest level using a screw on the vertical pole</li><li>b. Place beaker with liquid under the spindle</li><li>c. Lower the viscometer until the spindle is submerged to <u>the spindle's mark</u></li><li>d. <u>Optional (if used)</u>: Submerge the thermometer to the liquid</li></ol>	
<p>6. Measuring</p> <ol style="list-style-type: none"><li>a. Using "Enter", "Up", and "Down": select spindle type and speed</li><li>b. Press "Start"</li><li>c. Use "Enter" to change the speed</li><li>d. Use "Stop" to stop the process</li></ol>	
<p>7. <u>Notes</u></p> <ol style="list-style-type: none"><li>a. Wait for 30-60 sec before reading</li><li>b. Good results are in range 60%-80% of torque</li><li>c. Viscometer with beep (and indicate "Error") if under/over loaded</li><li>d. Results depend on beaker and volume of liquid</li><li>e. Use the same beakers for comparison measurements</li></ol>	

8. Disassembly/Cleaning
  - a. Turn off the viscometer
  - b. Disassemble the viscometer
  - c. Clean the spindle and frame (if used) with cleaner according to MSDS of liquid used
  - d. Return the components to the case
  - e. Return the case to the drawer

